	Туре	L#	Hits	Search Text	DBs	Time Stamp
1	BRS	L1	152718	(charge ADJ coupled) OR CCD	US- PGPUB; USPAT; EPO; JPO; DERWE NT; IBM_TD B	2005/05/17 15:54
2	BRS	L2	21912	(dark OR dummy OR idle) WITH (read\$3 OR readout)	US- PGPUB; USPAT; EPO; JPO; DERWE NT; IBM_TD B	2005/05/17 15:54
3	BRS	L3	2518	1 AND 2	US- PGPUB; USPAT; EPO; JPO; DERWE NT; IBM_TD B	2005/05/17 15:54
4	BRS	L4	3925	(read\$3 OR readout) WITH (interrupt\$3 OR suppress\$3 OR stop\$4 OR halt\$3 OR cancel\$4) WITH (trigger\$3 OR gat\$3)	US- PGPUB; USPAT; EPO; JPO; DERWE NT; IBM_TD B	2005/05/17 15:55

	Type	L#	Hits	Search Text	DBs	Time Stamp
5	BRS	L5	56		US- PGPUB; USPAT; EPO; JPO; DERWE NT; IBM_TD B	2005/05/17 15:55
6	BRS	L6	108541	(read\$3 OR readout) WITH (interrupt\$3 OR suppress\$3 OR stop\$4 OR halt\$3 OR cancel\$4)	US- PGPUB; USPAT; EPO; JPO; DERWE NT; IBM_TD B	2005/05/17 15:55
7	BRS	L7	622	3 AND 6	US- PGPUB; USPAT; EPO; JPO; DERWE NT; IBM_TD B	2005/05/17 15:56
8	BRS	L8	1820168	trigger\$3 OR gat\$3 OR interrupt\$3	US- PGPUB; USPAT; EPO; JPO; DERWE NT; IBM_TD B	2005/05/17 15:57

	Type	L#	Hits	Search Text	DBs	Time Stamp
9	BRS	L9	453	7 AND 8	US- PGPUB; USPAT; EPO; JPO; DERWE NT; IBM_TD B	2005/05/17 15:57
10	BRS	L10	269082	(x ADJ (ray OR radiation)) OR xray	US- PGPUB; USPAT; EPO; JPO; DERWE NT; IBM_TD B	2005/05/17 15:58
11	BRS	L11	58	9 AND 10	US- PGPUB; USPAT; EPO; JPO; DERWE NT; IBM_TD B	2005/05/17 15:58